


CORNER RECORD

City of Berkeley

Document Number CR 1806
County of Alameda, California

Brief Legal Description San Antonio Avenue



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒
Date of Survey 7/24/02

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Standard City of Berkeley street monument on San Antonio Avenue approximately 310' southwest of the intersection of San Antonio Avenue and Arlington Avenue. The monument was referenced using local ties. See reverse.

A description of the physical condition of the monument as found and as set or reset: _____
Iron pin in monument well left as found.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on September 5, 2002
Signed [Signature] P.L.S or R.C.E. No. L.S. 6884

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-1-03
and examined and filed 4-21-03
Signed [Signature] P.L.S or R.C.E. No. 5726
Title COUNTY SURVEYOR

County Surveyor's Comment _____

