

CORNER RECORD

COUNTY OF MONO T. 1N/S R. 26E MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☒ City of L.A.
 CORNER IDENTIFICATION - DATE OF VISIT 28 Aug 1975

34	35
3	2

$\frac{1}{4}$ Corner South 35

Described by M. Allstead

CORNER - LEFT AS FOUND ☒ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 The $\frac{1}{4}$ corner is a 2" diam. galvanized pipe with a galvanized cap threaded on top. The cap has inscribed on it "L.S. 3615" on the top and "D.W. & P." The pipe is 1.2 \pm ft above ground in a large open flat free of sage brush 150 \pm yds N of Hwy 120. There is an abandoned shed 120 \pm ft NE of $\frac{1}{4}$ corner.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
 STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



Abandoned shed, wood and corrugated metal construction, 120 \pm ft NW of $\frac{1}{4}$ corner

$\frac{1}{4}$ corner in open grass and sandy area surrounded by 6 lath with blue & yellow flagging.

Highway 120, 450 \pm ft S of corner

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Aug-28 19 75

SIGNED: [Signature]

L.S. or R.C.E. No.: [Signature]

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED _____ 19 _____

BY: _____

TITLE: _____

DOCUMENT No. 11126-25-C

STATEMENT ON BACK OF SHEET

YES ☐ NO ☐